

TIMBER PATCHES FOR REPAIRS OF GLULAM, FIR TIMBER

SURFACE REPAIR PATCHES - FOR ATEU0500 MILLING CUTTER

CODE	type/width [mm]	L		pcs
		[mm]	[in]	
FLI2070	F20	70	2 3/4	50
FLI20150	F20	150	6	30
FLI20300	F20	300	11 3/4	25
FLI20500	F20	500	19 3/4	25
FLI2470	F24	70	2 3/4	50
FLI24150	F24	150	6	30
FLI24300	F24	300	11 3/4	25
FLI24500	F24	500	19 3/4	25
FLI3570	F35	70	2 3/4	50
FLI35150	F35	150	6	20
FLI35300	F35	300	11 3/4	25
FLI35500	F35	500	19 3/4	25
FLI4270	F42	70	2 3/4	50
FLI42150	F42	150	6	20
FLI42300	F42	300	11 3/4	25
FLI42500	F42	500	19 3/4	25



CORNER PATCH - for ATEU0500 milling cutter


CODE	type/width		L		pcs
	[mm]	[in]	[mm]	[in]	
FLI3595	35	1 3/8	95	3 3/4	100



FLI types F20; F24, F35 and F42, as well as FLI3595 for the ATEU0500 milling cutter in the previous "TOOLS FOR TIMBER CONSTRUCTION" catalogue (valid until 2025) are not compatible with the PATCHILLO milling cutter.

SURFACE REPAIR PATCHES IN SPRUCE - FOR PATCHILLO MILLING CUTTER

CODE	L		B		s		pcs
	[mm]	[in]	[mm]	[in]	[mm]	[in]	
FLI151375	75	2 15/16	15	9/16	13	1/2	150
FLI1513250	250	10	15	9/16	13	1/2	195
FLI1515500	500	19 3/4	15	9/16	13	1/2	75
FLI451375	75	2 15/16	45	1 3/4	13	1/2	200
FLI4513250	250	10	45	1 3/4	13	1/2	75
FLI4513500	500	19 3/4	45	1 3/4	13	1/2	50



CORNER PATCH - for PATCHILLO milling cutter

CODE	L		B		pcs
	[mm]	[in]	[mm]	[in]	
FLI4590	90	3 1/2	45	1 3/4	130
FLI45250	250	10	45	1 3/4	63
FLI45500	500	19 3/4	45	1 3/4	50

On request, FLIs can also be supplied in larch and Oregon pine.



PATCHILLO PATCH MILLING MACHINE

See the product on page 223

